




**Quick Reference**

**Clinotronic S**

**Release 4.0**

**Control elements**



- 1 Screen
- 2-5 Membrane keyboard
- 6 Akku cover
- 7 USB-Connection
- 8 wylertRIGGER


**Charging of Clinotronic S**



- Connect the Clinotronic S with the power supply using the cable
- Plug the charger into a power outlet (100-240V~)

**Important:** Press to start charging the device.  
It does **not** start charging automatically!  
It is not possible to measure in charging mode!

**Overview Screen, Keyboard**



- 1 Screen
- 2 Serial number; 2a IR-number +red blin
- 3 Display of angle (depending on the selected unit)
- 4 Radio activated,
- 5 Charging indicator
- 6 Type of measurement: ABS=Absolute; REL=Relativ Zero
- 7 Local gravity is set.
- 8 Calibration performed with Clinomaster
- 9 Optical display of the entire measurement range
- 10 Optical display of the angle range close to zero
- 11 Gradient triangle and plus / minus signs according to inclination

**12 Units**

13 On/Off Menu: Arrow Pfeil upwards

14 Menu Menu: Enter, Submenu: Cursor to the right

**15 Arrow downwards**

Short cut "Relative Zero"


**16 Cancel**

Menu: Cursor left

**Power on:** Press the button (13) the screen will start immediately.

**Switch off:** Press the button (13) until the message appears: **Power off**

**Menu:** Press the button (14) to get Menu "Settings"




Menupoints:

- Device
- Unit
- Measurement
- Device Information

- Use the up arrow and down arrow to move the cursor up and down.
- Use to select the desired menu item in the menu
- Use the "Back" button to return to a menu level or to return to the measuring mode.

**Reversal Measurement (elimination of zero drift)**

Enter with the Menu "Measurement". Choose with "Absolute Zero"



After that:

The menu guides you live through the reversal measurement.

**For more information, read the manual at [www.wylerag.com](http://www.wylerag.com)**