
Release Notes
wylerSOFT

Version	Release Date	Release Notes
2.5.0.203	**2026.06.23**	• Improved Detection for wylerCONNECT Rev. C
2.4.16.188	**2026.01.27**	• Fixed version detection for wylerINSERT.
2.4.15.181	**2025.07.18**	• Updated wybus to 2.3.14.91 (Clinotronic S support)
2.4.13.160	**2025.04.07**	• Update wylerLicense to ensure it correctly reads dinkeyDongle
2.4.12.140	**2025.06.04**	• Update Firmware package to 1.0.8.8: • BlueLEVEL II Firmware update 1.0.16.0
2.4.11.134	**2025.05.12**	• wybus updated to 2.3.13.82 • New license request routine
2.4.10.102	**2025.02.12**	• New Installation routine • Improved software detection for wylerSPEC
2.4.8.74	**2024.12.05**	• Fixed version detection for new software version.
2.4.8.71	**2024.07.31**	• Removed SCS and Ilac Icon • Removed link to Wyler website • Updated device firmware package to 1.0.8.4 • Read correct version of wylerPLOT
2.4.7.3	**2023.11.13**	• wylerExplorer 2.4.2.0 • wylerInsert 2.5.2.0
2.4.7.0	**2022.12.14**	• wylerLICENSE update: wyerELEMENTS license is correctly on Dinkey Dongle Pro is now correctly identified
2.4.6.0	**2022.11.30**	• GUI corrections
2.4.5.0	**2022.10.31**	• wylerSPEC has now 12 modules 
2.4.4.0	**2022.09.26**	• wylerSOFT not installed automatically with other software products anymore

		• New wylerEXPLORER integrated
2.4.3.0	**2022.09.07**	• Bug fix in wylerEXPLORER: Device sampling fixed
2.4.2.0	**2022.09.02**	• New wylerEXPLORER (64 bit version) with notes regarding firmware updates • General bug fixes
2.4.1.0	**2022.08.12**	• wylerPLOT tab integrated in wylerSOFT
2.3.0.0	**2022.05.19**	• New wylerEXPLORER with BlueLEVEL II integration
2.2.18.0	**2022.04.27**	• Fix in wylerLICENSE: if Outlook is not installed, a zip file with current licenses and license request will be generated
2.2.17.0	**2022.04.26**	• Added missing 64-bit redistributable in installer
2.2.16.0	**2022.04.12**	• Integrated new wylerLICENSE for wylerPLOT license request