

Software Versionen LabEXCEL

Version	Date	Changes
3.05.02.33	13.08.2014	Bug fixes: - Sometime Connect Devices did not work
3.05.02.32	27.05.2014	Bug fixes: - Crash when Acrobat Reader XI is installed
3.05.02.31	27.05.2014	Bug fixes: - Disorder of sensors when connected via Bluetooth corrected. - Save data did sometimes not work.
3.05.02.30	29.04.2014	Changes: - New WyBus.dll Version 1.1.0.430, problem reading only one Sensor solved - Save Report when disconnect devices
3.05.02.29	18.11.2013	Changes: - New WyBus.dll Version 1.1.0.401, problem reading values from LM2000 solved
3.05.02.28	11.09.2013	Changes: - New WyBus.dll Version 1.1.0.393
3.05.02.27	19.10.2012	Bug fixes: - Data sampling improved. - Initial path to csv corrected - Initial csv separator set to ;
3.05.02.26	20.6.2012	Bug fixes: - Small changes Version Clino.
3.05.02.25	15.06.2012	Bug fixes: - Inconsistencies with csv save path resolved.
3.05.02.24	30.05.2012	Changes: - Resynchronization removed Bug fixes: - ZeroOffset Data check improved, Button"Set Values" turns green when values ok. - Buffer Restart improved. Known bugs: - Loss of data during automatic restart of measurement in the range from 2s to 5s.
3.05.02.23	18.04.2012	Changes: - .csv separator char is stored. Known bugs: - Out of memory crash when program is running long time at a high sampling rate - Deselected Sensors in between the select devices list causes misalignment in the graph and the .csv file. Open issues: - Bug fixes: -
3.05.01.22	8.03.2012	Bug fixes: - Limitation +-12° removed
3.05.01.20	19.05.2011	Changes: - Direct export into Excel removed due to compatibility problems. Instead data is written into a .csv file. - Write Zero Offset accepts list of sensors. - Known bugs: - Open issues: - Bug fixes:

		<ul style="list-style-type: none">- Data acquisition improved. Missing data is caused by hardware.- Missing values replaced with NaN.
--	--	--